CVe Monitor Cloning

Requirements: Installed & Configured OnDemand Software, the source Monitor with the data to be copied, the new (destination) Monitor, 1 USB 2.0 to Type B Mini (Progressive Cable Catalog Number CVEL-DATA9, which can be ordered at customerservice@procomps.com) cable to connect the Monitor to you PC.

1. Contact HelpDesk@ASTTech.com and provide them with the Device ID for the source Monitor and the new Monitor. They will respond with a passcode to copy the Monitor. **COPY** the passcode to your clipboard.

2.

Source Monitor

3. Support → Unlock Password → Paste



4. 

5. 

Source Monitor

6. 

Source Monitor

7. 

8. 

ALWAYS 0 When Cloning

9.

Enter info from Source Monitor.

10. 

11. 

For complete OnDemand software instructions, please refer to the User Guide.
For technical assistance please email: helpdesk@asttech.com.

© 2018 AST Technology North America
All rights reserved.